

Quick Check of Cisco Catalyst 9500 Switches

Product ID	Total Ports	Gigabit Ethernet / FE ports	Power Supply	SFP Ports	Rate	Uplink Interfaces	Rate	Forwarding bandwidth	Forwarding rate
C9500-32C	32	0	C9K-PWR-1600WAC-R	32	100G	N/A	N/A	6.4Tbps	2Bpps
C9500-32QC	32	0	C9K-PWR-650WAC-R	32	40G	N/A	N/A	3.2Tbps	1Bpps
C9500-48Y4C	52	0	C9K-PWR-650WAC-R	48	25G	4	100G	3.2Tbps	1Bpps
C9500-24Y4C	28	0	C9K-PWR-650WAC-R	24	25G	4	100G	2Tbps	1Bpps
C9500-24Q	24	0	PWR-C4-950WAC-R	24	40G	N/A	N/A	1920Gbps	1440Mpps
C9500-12Q	12	0	PWR-C4-950WAC-R	12	40G	N/A	N/A	960Gbps	720Mpps
C9500-40X	40	0	PWR-C4-950WAC-R	40	10G	Modular uplink options	N/A	960Gbps	720Mpps
C9500-16X	16	0	PWR-C4-950WAC-R	16	10G	Modular uplink options	N/A	480Gbps	360Mpps
C9500X-28C8D	36	0	C9K-PWR-1500WAC	28	100G	8	400G	12Tbps	8Bpps

HONGKONG YEJIAN TECHNOLOGIES CO., LTD

WWW.ROUTER-SWITCH.COM

Email: sales@router-switch.com (Sales Inquiries)

ccie-support@router-switch.com (Expert Technical Support)

partner@router-switch.com (Cooperative Partner)

Tel: +1-626-655-0998 (USA)

+852-3069 1898 (Hong Kong)

+852-3069 1868 (Hong Kong)

Address: RM 605 6/F FA YUEN COMM BLDG 75-77 FA YUEN ST MONGKOK KL, Hong Kong

Country: China

Branch: Router Switch Ltd.

Address: 3592 Rosemead Blvd, B #220 Rosemead, CA 91770 USA

Country: USA

Branch: Router Switch Ltd.

Address: Third Floor 207 Regent Street London W1B 3HH

Country: United Kingdom

Follow Us:

Facebook: [@Routerswitchdotcom](https://www.facebook.com/Routerswitchdotcom)

LinkedIn: [Router-switch.com](https://www.linkedin.com/company/Router-switch.com)

Twitter: [@routerswitchcom](https://twitter.com/routerswitchcom)

Youtube: [RouterSwitchcom](https://www.youtube.com/RouterSwitchcom)